Certificate of Compliance

Date Created/Modified: JUN 30,2010

This is to certify that the product listed below has been tested in accordance with the following laws and governmental regulations, including the CPSIA of 2008.

Mandatory Tests Performed (mark applicable box): ✓ ASTM F963 Physical/Mechanical Test ✓ ASTM F963 Flammability Test ✓ ASTM F963 Heavy Metal Test ✓ Substrate Lead / Lead in Paint 16 CFR Testing (CPSC Testing) ✓ Phthalates CPSIA 108 Art Materials (Labeling of Hazardous Art Materials) ✓ Other (please specify): EN71 PT 1,2,3, EU PHTHALATES No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL						
✓ ASTM F963 Flammability Test ✓ ASTM F963 Heavy Metal Test ✓ Substrate Lead / Lead in Paint CPSIA 101 16 CFR Testing (CPSC Testing) CPSIA 108 ✓ Phthalates CPSIA 108 Art Materials (Labeling of Hazardous Art Materials) 16 CFR 1500.14(b)(8) ✓ Other (please specify): EN71 PT 1,2,3, EU PHTHALATES No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL	√ ASTM F					
✓ Substrate Lead / Lead in Paint CPSIA 101 16 CFR Testing (CPSC Testing) CPSIA 108 ✓ Phthalates CPSIA 108 Art Materials (Labeling of Hazardous Art Materials) 16 CFR 1500.14(b) (8) ✓ Other (please specify): EN71 PT 1,2,3, EU PHTHALATES No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL						
16 CFR Testing (CPSC Testing) ✓ Phthalates CPSIA 108 Art Materials (Labeling of Hazardous Art Materials) 16 CFR 1500.14(b)(8) ✓ Other (please specify): EN71 PT 1,2,3, EU PHTHALATES No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL						
 ✓ Phthalates ✓ Art Materials (Labeling of Hazardous Art Materials) ✓ Other (please specify): EN71 PT 1,2,3, EU PHTHALATES No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL 						
Art Materials (Labeling of Hazardous Art Materials) ✓ Other (please specify): EN71 PT 1,2,3, EU PHTHALATES No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL	16 CFR					
✓ Other (please specify): EN71 PT 1,2,3, EU PHTHALATES No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL	•					
No Test Requested by Importer Item #: EDX-62 Item Description: OH CLOCK DIAL	Art Materials (Labeling of Hazardous Art Materials)					
Item #: EDX-62 Item Description: OH CLOCK DIAL	√ Other (
	No Test Requested by Importer					
Item Specs: OH CLOCK DIAL (11.7 CM, 5PCS)						
City of Factory: Taipei						
Country of Factory: Taiwan						
Date Manufactured: MAY, 2010	Date Ma					
Importer Name: Marvel Education Company	Imp					
Address: 82 Wall St. Suite 1105						
New York, NY 10005						
Tel: <u>212-662-7005</u>						
Testing Facility: Intertek, Taiwan Contact Name: Louise Lin	Toci					
Address: 8F. NO.423, RUIGUANG RD. NEIHU DISTRICT, TAIPEI CITY, TAIWAN, R.O.C.	1681					
Address. 8F. NO.423, RUIGUANG RD. NEIHO DISTRICT, TAIPET CTTY, TAIWAN, R.O.C.						
Tel: 886 - 2 - 6602-2214						
Testing Date(s): 2-Feb-09	Tost					
Testing Date(s):						
A copy of this report will be maintained by:	1031					
Name: Debra Porter Tel: 212-662-7005						
Email: marvel_ed@yahoo.com						
Address: 82 Wall St. Suite 1105						
New York, NY 10005	Addi ess:					