

# Certificate of Compliance

Date Created/Modified: JAN 3,2012

This is to certify that the product listed below has been tested in accordance with the following laws and governmental regulations, including the CPSIA of 2008.

Mandatory Tests Performed (mark applicable box):	
<input type="checkbox"/>	<b>ASTM F963</b> Physical/Mechanical Test
<input type="checkbox"/>	<b>ASTM F963</b> Flammability Test
<input checked="" type="checkbox"/>	<b>ASTM F963</b> Heavy Metal Test
<input checked="" type="checkbox"/>	Substrate Lead / Lead in Paint <b>CPSIA 101</b>
<input type="checkbox"/>	<b>16 CFR</b> Testing (CPSC Testing)
<input type="checkbox"/>	Phthalates <b>CPSIA 108</b>
<input type="checkbox"/>	Art Materials (Labeling of Hazardous Art Materials) <b>16 CFR 1500.14(b)(8)</b>
<b>Other</b> (please specify):	
<b>No Test Requested by Importer</b>	

Item #: MX383 Item Description: PULL BACK EMERGENCY VEHICLES  
 Item Specs: \_\_\_\_\_

City of Factory: SHANTOU  
 Country of Factory: CHINA  
 Date Manufactured: NOV 06, 2011

Importer Name: US Toy Company  
 Address: 13201 Arrington Rd  
Grandview, MO 64030  
 Tel: (816) 761-5900

Testing Facility: Intertek Contact Name: Karen S. C. Ng  
 Address: 2/F, Garment Centre, 576 Castle Peak Road,  
Kowloon,  
Hong Kong.  
 Tel: 852 2173 8888

Testing Date(s): OCT 27, 2011 Test Report #: HKGH01233022

A copy of this report will be maintained by:  
 Name: Courtney Peterman Tel: (816) 761-5900 ext 2420  
 Email: [capeterman@ustoyco.com](mailto:capeterman@ustoyco.com)  
 Address: 13201 Arrington Rd Grandview, MO 64030

